Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins/Russo			Date(s):	20-Dec-19
Company/Owner:	Inte	ermountain Gas Company	y Uni	it/OPID:	8160
		•	<u></u>	•	0_00
Inspection Type & Time (1	day)		Total Inspec	ction Days:	2
Standard: Construction: 2 Training: (T)(D) Integrity Management: Incident:					
M/M: Follow-up:	OQ:	Damage Preve	ntion:	D&A:	
Inspection Summary					
A construction inspection was	s performed or	n Das-co, a contractor for	Intermountain	Gas Compar	ny.
28 Oct 2019: (2.0 Construction Observed a Dasco crew exceptusing crew we noticed that procedural requirement. Proceeded to check the tempore of what had taken place and fuser, and made the site safe	they were not ior to the next and I asked to ps and it was a GC procedure.	t checking the iron tempt the fuse I asked them to show the calibration of the calibratio	perature prior to now me what the date and it was 50 degrees, and acted IGC leader to stop the job	to fusing as the temperate within special the require ership and in the term of the term o	per IGC ure of the iron cs. They then ed temps are informed them
Areas observed during this pro	oject were: Ex	cavating and Fusing			
Attachments: IPUC Form 4 Construction Inspections Das-co Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.					
Corrective Action Required:	NOPV	Follow-up Required:	Yes X	No	
Yes X No		-		10-Feb-20	
Inspector (Lead): Bruce Perkins	1.16%	Pak. A	Date		
Reviewer:	THE STATE OF THE S	EMPT I	The second second second second second	/20/2019	
Darrin Ulmer	1 mis	1/1/1///	Date		ne 2019
	- 11 X W	VI VI VI		~5 T	00 2019